

## **PDBK-101 Ethernet Option Board Software Version 1.81 for HD XDCAM Decks**

This software should only be done if the Deck software has been upgraded to Version 1.93 or higher.

This Software upgrade addresses the following issues:

The syntax error is returned to the [FTP] ABOR command.

This bug has been fixed.