

Software Version PKG 1.60 – AT 1.60 Features and Fixes

These camcorders when upgraded will have the follow issues addressed.

1. The RCP-70X/73X and the MSU-700/900 have been supported.
2. The convergence accuracy of ATW (Auto Tracing White Balance) has been improved.
3. Bug Fix of DCC MENU
The value of M13 DCC ADJUST in the [MAINTENANCE] menu is reset when turning off the power and turning it on again.
This bug has been fixed.