



PMW-EX30 Version 1.26 Upgrade

Major functions updated with v1.26:

- ✓ Improved SxS recording reliability with SxS-1 media.
- ✓ Upon installation of this new software, support of the new SBS-32G1A/64G1A memory cards is greatly improved. These cards offer longer recording times (e.g. the 64GB card provides 200 minutes at 35Mbps) and increased data transfer speeds of 1.2 Gbps. These cards may require new drivers when they are used to transfer / edit material via a PC or Mac.

Please visit <http://pro.sony.com/bbsc/ssr/cat-recmedia/cat-recmediaxdcamex/resource.downloads> for additional information.

Notes:

- This update must be installed by a Sony Factory Service Center, and is **FREE OF CHARGE** to existing PMW-EX30 users.
- Shipment/transportation to the Sony service center is the user's responsibility.
- Shipment of the PMW-EX30 back to the end user will be **FREE OF CHARGE**.

***USB Added Functionality:**

- As a result of Sony's constant efforts to improve our products, we are now offering, also **FREE OF CHARGE** to PMW-EX30 end-users, a field modification to the PMW-EX30. This field modification will **add external USB functionality** to allow end-users to perform their own software upgrades as they become available. When you decide to send in your PMW-EX30 for this latest firmware upgrade, Sony will, at no extra charge to you, add the external USB port to the upper right corner of the top surface of the unit's outer cabinet.

***This offer is valid through March 31, 2012**

Please contact your local Sony Service Center for further details.

<u>Eastern Service Facility</u> Teaneck Sony Service Center Sony Electronics Inc. 123 W. Tryon Avenue Teaneck, New Jersey 07666 Voice: 201-833-5300 FAX: 201-833-5312 TeaneckService@am.sony.com	<u>Western Service Facility</u> Los Angeles Sony Service Center Sony Electronics Inc. 2706 Media Center Drive; Suite 130 Los Angeles, California 90065 Voice: 323-352-5000 FAX: 323-352-5039 LAService@am.sony.com
---	---